

# Product Safety Recall

## IBS & Protex Disc Brake Rotors

Designed for fitment on the front axle of select Isuzu D-Max and Holden Colorado models manufactured from 2011

**ONLY:**

Part Number BR16040, with Batch Codes ending in KP, EQ or ER

OR

Part Number DR12909, with Batch Codes ending in KP, AQ, CQ, HQ, ER, DQ or GP

PROTEX DR12909  
Batch Codes Ending in: KP, AQ, CQ, HQ, ER, DQ or GP



IBS BR16040  
Batch Codes Ending in: KP, EQ or ER



**Distributed by Specialist Wholesalers Pty Ltd t/a AAD  
Sold from 9 August 2017 to 12 December 2019**

**DEFECT:** Due to improper manufacture, the disc brake rotor hub may crack.

**HAZARD:** If the disc brake rotor hub cracks, the brakes may not function correctly or may fail, posing an accident and injury risk to the vehicle occupants and other road users.

**WHAT TO DO:** Consumers should immediately stop using the affected products, or vehicles that have been fitted with an affected product, and contact the place of purchase for instructions on obtaining a replacement or refund.

Where an affected product has been fitted onto a vehicle, consumers should have the disc brake rotor(s) replaced by a qualified mechanic, free of charge. Affected products that have not been fitted to vehicles may be returned to the consumer's place of purchase for a full refund.

**CONTACT:** Consumers can contact AAD by phoning 03 8369 1400 (Monday - Friday 9:00am - 5:00pm) or via email at [info@aad.com.au](mailto:info@aad.com.au).

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**